Mill Creek Fish Passage Improvements

Joe Pecharich and Bob Pagliuco NOAA Restoration Center




Barrier #1 – Modified waterfall and "sacrete" passageway



Modified waterfall – boulder placed created an ~6-7 foot jump with only 2-3 feet of depth





"Sacrete" filled passageway 10-4-2012




Once landownership changed.....

3 people, 1 pry bar, 2 sledgehammers, 6-7 hours.....









Waterfall area with "passage flows" - before




Waterfall area with "passage flows" - after



Monitoring Results – before removal



Monitoring Results – after removal




Barrier #2 – Large Flashboard Dam w/ Sill


blocks ~ 90% passage to 11.3 miles of habitat (~62% of the watershed) for coho and steelhead



Spawner Surveys 2011-2015



Preferred Alternative – Alt. E



Preferred Alternative – Alt. E

- 3% roughened chute side-channel providing passage for all adults and most juveniles
- Will be the new low flow channel
- Dam will be cut down 12- 18 inches to water side-channel
- Extremely complicated area landowners, house above the creek, 4 water diversions above (also being worked on!), natural creek constriction, etc.

Where we are at and next steps

- NOAA Restoration Center is looking at how much funding to contribute after funding designs
- Trout Unlimited and Prunuske-Chatham, Inc. to submit to FRGP and others...
- If funding comes through 2016 removal??
- This has been an 8 year effort Thanks to Derek Acomb, Lauren Hammack, Mary Ann King and Mariska Obedzinski and many others!