



Aikens (2019)

Before and after treatment



Boise (2019)

Before and after treatment



Camp (2019)

Before and after treatment



East Fork Swimmer's Dam (2019)
Before and after treatment



Elk (2019)
Before and after treatment



Fort Goff (2019)
Before and after treatment



Grider (2019)

Before and after treatment

Knownothing (2019)

Before treatment (middle row)
&
After treatment (bottom row)





**Little North Fork
(2019)**
Before and after treatment



Nordheimer (2019)
Before treatment (middle row)
&
After treatment (bottom row)



Oak Flat (2019)

Before and after treatment



Plummer (2019)

Before & after treatment
(bottom row)



Rock Creek (2019)

Before and after treatment (left column)



Volunteers joined MKWC for the Rock Creek Fish Passage and Brush Bundling Work Day (right column)



Slate (2019)

Before and after treatment



South Russian (2019)

Before and after treatment



Stanshaw (2019)

Before and after treatment



Wooley (2019)

**Rios to Rivers Students &
Educators**





Aikens (2020)

Before and after treatment



Black Bear (2020)

Before and after treatment



Boise (2020)

Before and after treatment




Camp (2020)
Before and after treatment
(top row)

China (2020)
Before and after treatment
(middle row)



Coon (2020)
Before and after treatment
(bottom row)



Cronan (2020)

Before and after treatment



Youth Environmental Summer Studies program volunteers improved fish passage and added brush bundles for cover at Cronan Gulch



Dillon (2020)

Before and after treatment



East Fork Elk (2020)

Before and after treatment



Elk (2020)

Before and after treatment



Elliot (2020)

Before and after treatment



Fort Goff (2020)

Before and after treatment




Independence (2020)

Before and after treatment



Indian (Klamath) (2020)

Before and after treatment



Irving (2020)

Before and after treatment



Jones (2020)

Before and after treatment



Youth Environmental Summer
Studies program volunteers
improved passage for juvenile
fish at Jones Gulch

King (2020)
Before and after treatment
(top row)



Knownothing (2020)
Before and after treatment
(middle row)





Little Horse (2020)
Before and after treatment
(bottom row)



Little North Fork (2020)

Before treatment (left
column) and after treatment
(middle column)



Youth Environmental Summer Studies program volunteers learned to identify salmonid species with SRRC fisheries crew members at Little North Fork (right column)



Methodist (2020)
Before and after treatment



Mill (2020)
Before and after treatment




Nordheimer (2020)

Before and after treatment



SRRC, MKWC, and Karuk Fisheries met for a fish passage training and knowledge exchange at Nordheimer Creek




Oak Flat(2020)

Before and after treatment



Plummer (2020)
Before and after treatment



Portuguese (2020)
Before and after treatment



Red Cap (2020)
Before and after treatment



Rock (2020)

Before and after treatment



Rogers (2020)

Before and after treatment




Sainte Claire (2020)

Before and after treatment



Sandy Bar (2020)
Before and after treatment
(top row)



Slate (2020)
Before and after treatment
(middle row)




South Russian (2020)
Main channel (no treatment
needed) and side channel
(treated)
(bottom row)



Stanshaw (2020)

Before and after treatment




Swillup (2020)

Before and after treatment



Thompson (2020)
Before and after treatment



Ti (2020)
Before and after treatment